

H  
County Surveyor's Record, Douglas County, Oregon

West Bdy. of T. 23 S., R. 1 W.

CHAINS 38.50	Creek, 3 lks. wide, course NE Ascend	-200
40.00	Set basalt stone, 18x8x6 ins. 14 ins. in the ground, for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on W face, from which A cedar, 18 ins. diam., bears S.18*E., 50 lks. dist. Marked $\frac{1}{4}$ S B T A fir, 24 ins. diam., bears N.61*W., 25 lks. dist. Marked $\frac{1}{4}$ S B T	
55.50	Top of spur, course E Descend	+300
73.40	The old sec. cor. which I destroy	
80.00	Set a post, 4 ft. long, 4 ins. sq. 24 ins. in the ground, for cor. to secs. 25, 30, 31 and 36 marked T 23 S S 30 on NE., R 1 W S 31 on SE., R 2 W S 36 on SW., and S 25 on NW faces with 1 notch on S and 5 notches on N edges, from which A cedar, 20 ins. diam., bears N.16*E., 36 lks. dist. Marked T 23 S R 1 W S 30 B T A fir, 30 ins. diam., bears S.56*E., 17 lks. dist. Marked T 23 S R 1 W S 31 B T A cedar, 20 ins. diam., bears S.72*W., 58 lks. dist. Marked T 23 S R 2 W S 36 B T A fir, 20 ins. diam., bears N.65*W., 37 lks. dist. Marked T 23 S R 2 W S 25 B T Land, mountainous, 80.00 chs. Timbered with fir and hemlock Dense undergrowth of vine-maple, and hemlock 80.00 chs. Soil, sandy and rocky, 3rd and 4th rate	
	North on W boundary of Sec. 30  Va. 20*E  Descending through timber Could find no trace of old $\frac{1}{4}$ sec. cor.	