

Subdivisions of T. 23 S., R. 1 W.

<p>CHAINS</p>	<p>A fir, 20 ins. diam., bears N.26*W., 30 lks. dist. Marked T 23 S R 1 W S 22 B T Land, mountainous, 80.00 chs. Timbered with fir and hemlock Dense undergrowth of vine-maple, and hemlock, 80.00 chs. Soil, sandy and rocky, 3rd and 4th rate July 14, 1894</p>	
<p>40.00 80.40 11.50 40.20 50.00 80.40</p>	<p>N.89*43'E. on random line between secs. 23 and 26 Va. 20*E. Set temp. 1/4 sec. cor. Intersect N and S line 14 lks. N of cor. to secs. 23, 24, 25 and 26, thence I run S.89*49'W. on true line between secs. 23 and 26 Va. 20*E. Ascending through timber Top of ridge bears NE and SW Descend Set a post, 4 ft. long, 4 ins. sq. 24 ins. in the ground, for 1/4 sec. cor., marked 1/4 S on N face, from which A laurel, 6 ins. diam., bears N.20*E., 23 lks. dist. Marked 1/4 S B T A fir, 10 ins. diam., bears S.11*W., 16 lks. dist. Marked 1/4 S B T Ravine, course N. Ascend To the cor. to secs. 22, 23, 26 and 27 Land, mountainous, 80.40 chs. Dense undergrowth of vine-maple and hemlock, 80.40 chs. Heavily timbered with fir and hemlock, 80.40 chs. Soil, sandy and rocky, 3rd and 4th rate</p>	<p>200 200</p>
	<p>Beginning at the cor. to secs. 33 and 34 on S boundary of Tp. thence I run N.0*3'W. bet. secs. 33 and 34 Va. 20*E. Ascending through timber</p>	