

Eastern Boundary of T. 23 S., R. 3 W., W.M.
 as surveyed by Deputy Surveyor James P. Currin
 under Contract No. 438, dated May 2nd, 1882

CHAINS

Beginning at the cor. to Tps. 23 and 24 S., Rs. 2 and 3 W., which is a post, 4½ ft. long, 4 ins. sq., 24 ins. in the ground, marked

T 23 S S 31 on NE., R 2 W S 6 on SE.

T 24 S S 1 on SW. and R 3 W S 36 on NW. faces with 6 notches on each edge, from which,

A Fir, 26 ins. diam., bears N.60*E., 22 lks. dist. marked T.23 S R 2 W S 31 B T.

A Vine-maple, 6 ins. diam., bears S.25*E., 44 lks. dist., marked T 24 S R 2 W S 6 B T.

A Vine-maple, 6 ins. diam., bears S.20*W., 23 lks. dist., marked T 24 S R 3 W S 1 B T.

A Fir, 26 ins. diam., bears N.45*W., 13 lks. dist. marked T 23 S R 3 W S 36 B T. I run

North on east bdy. of sec. 36.

Va. 18½*E.

Ascend through open timber.

40.00 Set a post, 3 ft. long, 4 ins. sq., 20 ins. in the ground for ¼ sec. cor, marked ¼ on W. face, from which,

A double Fir, 70 ins. diam., bears North, 8 lks. dist., marked ¼ S B T.

A Fir, 36 ins. diam., bears S.10*E., 80 lks. dist. marked ¼ S B T.

75.00 Summit of mountain

80.00 Set a post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for cor. to secs. 25, 30, 31 and 36, marked T 23 S S 30 on NE., R 2 W S 31 on SE.

R 3 W S 36 on SW. and S 25 on NW. faces with 5 notches on the north and 1 notch on south face, from which,

A Hemlock, 20 ins. diam., bears N.15*E., 66 lks. dist., marked T 23 S R 2 W S 30 B T.

A Spruce, 40 ins. diam., bears S.80*E., 13 lks. dist., marked T 23 S R 2 W S 31 B T.

A Hemlock, 10 ins. diam., bears S.85*W., 16 lks. dist., marked T 23 S R 3 W S 36 B T.

+
1000