

-9-

Northern Boundary of T. 24 S., R. 2 W., W.M.

## CHAINS

A Maple, 5 ins. diam., bears N.12\*W., 21 lks. dist.,  
marked  $\frac{1}{4}$  S B T.

A Maple, 6 ins. diam., bears S.60\*W., 15 lks. dist.,  
marked  $\frac{1}{4}$  S B T.

43.81 A Fir, 20 ins. diam.

49.30 A Fir, 36 ins. diam.

54.50 A brook, 3 lks. wide, course S.10\*W.

79.18 The corner to Tps. 23 and 24 S., Rs. 2 and 3 W.

Land, mountainous.

Soil, 3rd rate, densely covered with forest of Pine,

Fir, Hemlock, Maple, Laurel and Dogwood.

Thick undergrowth of Laurel, Hazel, Vine-maple,

Huckleberry and Sallal.

June 1st, 1883.

---

Southern Boundary of T. 23 S., R. 2 W., W.M.  
as surveyed by Deputy Surveyor Henry L. Chandler  
under Contract No. 619, dated June 5, 1893.

---

In subdividing this township, I commence by running  
S.89\*45'W. on the south boundary of section 36, the  
East boundary of this Tp. having been re-run by me,  
in the survey of T. 23 S., R. 1 W., and found to be  
5 miles, 64 chains and 50 lks. in length.

At 39.50 chains, I find the  $\frac{1}{4}$  sec. cor., 23 lks. S. of  
line, and at 78.75 chains, the sec. cor. bears south  
83 lks. dist.

I therefore, continue the same, course on and find that  
no part of the South boundary is in alignment and  
that the measurements are not the same as I make  
them, and find that when the range line between  
T. 24 S., Rs. 2 and 3 W. was run, the SE. cor. of  
T. 23 S., R. 3 W. was not found, and that the closing  
corner, which the notes furnished me by the Surveyor  
General, say was set 4.38 ch. West of the SE. cor. of  
Tp. 23 S., R. 3 W., was instead set 11.80 chs. West  
and 8.00 chs. North of the Tp. cor.