

County Surveyor's Record, Douglas County, Oregon

- 21 -

Subdivisions of T. 23 R. 2 W., W.M.

CHAINS	<p>marked $\frac{1}{4}$ S B T.</p>	
80.00	<p>Set a post, 4 ft. long, 4 ins. sq., 24 ins. in the ground, for cor. to secs. 25, 26, 35 and 36, marked T 23 S S 25 on NE.; R 2 W S 36 on SE. S 35 on SW and S 26 on NW. faces, with 1 notch on S. and E. edges, from which</p> <p>A Fir, 50 ins. diam., bears N.28*E., 15 lks. dist., marked, T 23 S R 2 W S 25 B T.</p> <p>A Cedar, 20 ins. diam., bears S.70*E., 57 lks. dist., marked T 23 S R 2 W S 36 B T.</p> <p>A Fir, 40 ins. diam., bears S.26*W., 20 lks. dist., marked T 23 S R 2 W S 35 B T.</p> <p>A Hemlock, 4 ins. diam., bears N.66*W., 17 lks. dist., marked T 23 S R 2 W S 26 B T.</p> <p>Land, mountainous.</p> <p>Heavily timbered with Fir and Hemlock.</p> <p>Dense undergrowth of Vine-maple and Rhododendron.</p> <p>Soil, sandy and rocky; 3rd and 4th rate.</p> <p style="text-align: right;">80.00 chains.</p>	
	<p>East on random line between secs. 25 and 36.</p> <p style="text-align: right;">Va. 20*E.</p>	
40.00	<p>Set temp. $\frac{1}{4}$ sec. cor.</p>	
80.20	<p>Intersect W. boundary Tp. 20 lks. South of cor. to secs. 25, 30, 31 and 36, Thence I run S.89*51'W. on true line between secs. 25 and 36.</p> <p style="text-align: right;">Va. 20*E.</p>	
	<p>Descending through heavy timber and brush.</p>	
12.25	<p>Creek, 1 lk. wide, course NW.</p>	
16.75	<p>Ravine, course NW., ascend</p>	-200
20.25	<p>Top of spur, course NW.</p> <p>Descend</p>	+100
28.60	<p>Creek, 1 lk. wide, course NW.</p> <p>Ascend</p>	-100