

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 23 S., R. 2 W., W.M.

CHAINS		
32.75	Top of spur, course NW., Descend	+ 75
36.75	Creek, 15 lks. wide, course NE. Ascend.	-100
40.00	Set basalt stone, 14 x 8 x 6 ins., 9 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N. face, from which. A Fir, 36 ins. diam., bears N.74*E., 47 lks. dist., marked $\frac{1}{4}$ S B T. A Cedar, 12 ins. diam., bears S.60*E., 19 lks. dist., marked $\frac{1}{4}$ S B T.	
42.75	Creek, 2 lks. wide, course NE.	
80.20	To the cor. to secs. 25, 26, 35 and 36. Land, mountainous. Heavily timbered with fir and hemlock. Dense undergrowth of Vine-Maple, Rhododendron and Hemlock. 80.20 chains. August 12, 1894.	
	N.0*1'W. between secs. 25 and 26. Va. 20*E. Descending through timber.	
17.00	Ravine, course NE. Ascend	-75
29.50	Top of spur, course NE. Ascend.	+150
40.00	Set basalt stone, 12 x 8 x 6 ins., 9 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on W. face, from which, A Fir, 40 ins. diam., bears N.63*E., 8 lks. dist., marked $\frac{1}{4}$ S B T. A Fir, 40 ins. diam., bears S.75*W., 20 lks. dist., marked $\frac{1}{4}$ S B T.	
52.50	Ascend	-200
67.50	Top of spur, course NW.	+200