

County Surveyor's Record, Douglas County, Oregon

27

Subdivisions of T. 23., R. 2 W., W.M.

CHAINS	Descend.	
75.10	Creek, 1 lk. wide, course NE., ascend.	-100
80.00	Set basalt stone, 24 x 6 x 5 ins., 18 ins. in the ground for cor. to secs. 22, 23, 26 and 27, marked with 2 notches on S. and E. edges, from which, A Cedar, 20 ins. diam., bears N.19*E., 23 lks. dist. marked T 23 S R 2 W S 23 B T. A Hemlock, 10 ins. diam., bears S.63*E., 27 lks. dist., marked T 23 S R 2 W S 26 B T. A Hemlock, 18 ins. diam., bears S.85*W., 39 lks. dist., marked T 23 S R 2 W S 27 B T. A Hemlock, 10 ins. diam., bears N.60*W., 53 lks. dist., marked T 23 S R 2 W S 22 B T. Land, mountainous. Heavily timbered with Fir, Hemlock, and scattering Cedar. Dense undergrowth of Vine-maple and Rhododendron. Soil, sandy and rocky; 3rd and 4th rate. 80.00 chs.	
	N.89*43'E. on random line between secs. 23 and 26. Va. 20*E.	
40.00	Set temp. $\frac{1}{4}$ sec. cor.	
79.80	Intersect N. and S. line, 40 lks. N. of cor. to secs. 23, 24, 25 and 26, thence I run, West on true line between secs. 23 and 26 Va. 20*E. Ascending through timber.	
5.25	Top of spur, course NW., descend.	75
32.25	Creek, 4 lks. wide, course NW., (ascend,)	-500
39.90	Marked a stone in place 30 x 30 x 24 ins., above ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N. face, from which, A Hemlock, 14 ins. diam., bears N.27*W., 6 lks. dist. marked $\frac{1}{4}$ S B T. A Hemlock, 16 ins. diam., bears S.43*E., 8 lks. marked $\frac{1}{4}$ S B T.	
46.50	Top of spur, course N. Ascend.	150