

County Surveyor's Record, Douglas County, Oregon

30-

Subdivisions of T. 23 S., R. 2 W., W.M.

CHAINS		
	A Fir, 36 ins. diam., bears S.35*E., 14 lks. dist., marked $\frac{1}{4}$ S B T.	
49.25	Enter same creek course W. from NE.	
53.25	Leave creek, course SW. Ascend.	-200
55.75	Top of spur, course SW. Descend.	+ 50
77.50	Same creek, 8 lks. wide, course NW. Ascend.	-200
80.40	To the cor. to secs. 27, 28, 33 and 34. Land, mountainous. Heavily timbered with Fir and Hemlock. Undergrowth, Vine-maple. Soil, sandy and rocky; 3rd and 4th rate. 80.00 chains.	+ 50
<hr/>		
	N.0*3'W. between secs. 27 and 28 Va. 20*E. Descending through timber.	
0.25	Creek, 8 lks. wide, course NW. Ascend.	- 10
40.00	On top of ridge, bears NW. and SE. Set a post, 4 ft. long, 4 ins. square, 24 ins. in the ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S on W. face, from which, A Hemlock, 8 ins. diam., bears S.82*E., 9 lks. dist., marked $\frac{1}{4}$ S B T. A Hemlock, 6 ins. diam., bears S.85*W., 11 lks. dist., marked $\frac{1}{4}$ S B T.	+350
80.00	Set basalt stone, 14 x 10 x 8 ins. 9 ins. in the ground for cor. to secs. 21, 22, 27 and 28, marked with 2 notches on S. and 3 notches on E. edges, from which, A Cedar, 24 ins. diam., bears N.65*E., 46 lks. dist., marked T 23 S R 2 S 22 B T.	-400