

County Surveyor's Record, Douglas County, Oregon

-33-

Subdivisions of T. 23 S., R. 2 W., W.M.

CHAINS

A Fir, 28 ins. diam., bears N.28*E., 31 lks. dist.,
marked T. 23 S R 2 W S 28 B T.

A Hemlock, 14 ins. diam., bears S.42*E., 31 lks. dist.,
marked T 23 S R 2 W S 33 B T

A Hemlock, 28 ins. diam., bears S.28*W., 48 lks. dist.,
marked T 23 S R 2 W S 32 B T.

A Cedar, 6 ins. diam., bears N.65*W., 37 lks. dist.,
marked T 23 S R 2 W S 29 B T.

Land, mountainous.

Heavily timbered with Fir and Hemlock.

Dense undergrowth of Rhododendron and Vine-maple.

Soil, sandy and rocky; 3rd and 4th rate.

80.00 chains.

August, 25, 1894.

East on random line between secs. 28 and 33.

Va. 20*E.

40.00 Set Temp. $\frac{1}{4}$ sec. cor.

80.15 Intersect N. and S. line, 14 lks. S. of cor. to secs.

27, 28, 33 and 34, thence I run,

S.89*54'W. on true line between secs. 28 and 33.

Va. 20*E.

Ascending through timber.

11.50 Top of spur, course N.

+ 50

Descend.

14.75 Creek, 5 lks. wide, course NE., Ascend.

- 50

22.50 Top of spur, course N.

+150

Descend.

25.25 Ravine, course N.

- 30

Ascend.

31.75 Top of spur, course N.

+ 50

Descend.

38.50 Creek, 1 lk. wide, course NW.

- 50

Ascend.