

County Surveyor's Record, Douglas County, Oregon

-38-

Subdivisions of T. 23 S., R. 2 W., W.M.

CHAINS		
	A Cedar, 20 ins. diam., bears N.30*W., 36 lks. dist., marked $\frac{1}{2}$ S B T.	
	A Fir, 40 ins. diam., bears S.45*W., 32 lks. dist., marked $\frac{1}{2}$ S B T.	
54.00	Creek, 1 lks. wide, course N. Ascend.	-150
55.50	Top of spur, course N. Descend.	+ 30
60.00	Bottom of spur, bears N. and S. Ascend.	-150
75.00	Top of spur, course NW. Descend.	+150
80.20	Ravine, course NW. Ascend.	- 75
80.60	To the cor. to secs. 29, 30, 31 and 32. Land, mountainous. Heavily timbered with Fir and Hemlock. Undergrowth, Rhododendron. Soil, sandy and rocky; 3rd and 4th rate. 80.60 chains.	+ 20
	West on random line between secs. 30 and 31 Va. 19*E.	
40.00	Set temp. $\frac{1}{4}$ sec. cor.	
68.25	Intersect West boundary of Tp. 9 lks. South of cor. to secs. 30 and 31, thence I run, S.89*56'E. on true line between secs. 30 and 31 Va. 20*E.	
	Descending through timber.	
2.75	Creek, 2 lks. wide, course SW.. ascend,	- 60
7.25	Top of spur, course SW. Descend.	+100
18.25	Ravine, course SW. Ascend.	-100
20.75	Creek, 1 lk. wide, course SW.	
27.25	Top of spur, course SW., descend	+ 50