

County Surveyor's Record, Douglas County, Oregon

- 42 -

Subdivisions of T. 23 S., R. 2 W., W.M.

CHAINS

A Hemlock, 7 ins. diam., bears N.8*W., 25 lks.
dist., marked $\frac{1}{4}$ S B T.

32.20 Creek, 1 lk. wide, course NW.

-100

Ascend.

42.30 Top of spur, course N.

+100

Descend.

68.30 To the cor. to secs. 19, 20, 29 and 30.

-300

Land, mountainous.

Heavily timbered with Fir, Hemlock, Cedar.

Undergrowth of Vine-maple and Hemlock.

Soil, sandy and rocky; 3rd and 4th rate.

68.30 chs.

General Description.

This township is rough and mountainous. Soil 3rd and 4th rate, sandy loam and stony and for the most part worthless for agricultural purposes.

It is chiefly valuable for its timber, there being a heavy growth of Fir, Hemlock, Maple and Cedar of good quality.

The entire township is covered with a dense undergrowth of Vine-maple, young Fir and Hemlock, Rhododendron, Chinquapin and Mountain balm.

There is one settler in Sec. 5 and one in sec. 8.

The township is well watered by the Coast Fork of Willamette and the Brumbaugh rivers and their tributaries.

Henry L. Chandler

U. S. Deputy Surveyor.