

South Boundary of T. 23 S., R. 3 W.

CHAINS	
	<p>Land covered with dense forest of fir, hemlock, & maple timber 80.00 chs.</p> <p>Thick underbrush of vine maple 80.00 chs.</p> <p style="text-align: right;">June 30, 1882</p>
	<p>East, on South Boundary of Sec. 33</p> <p style="text-align: right;">Var. 17*45' E.</p> <p>Through thick underbrush of hemlock</p>
7.50	Stream 2 lks. wide flows NE.
8.50	Stream 2 lks. wide flows N.
39.50	Stream 15 lks. wide flows S. supposed to be Calapooia
40.00	<p>A hemlock, 5 ins. diam., which I mark ⁺S. on N. face for $\frac{1}{4}$ sec. cor. from which</p> <p style="padding-left: 40px;">A cedar, 14 ins. diam., bears S.10 lks. dist. marked $\frac{1}{4}$ S B T</p> <p style="padding-left: 40px;">A hemlock, 14 ins. diam., bears E.20 lks. dist. marked $\frac{1}{4}$ S B T</p> <p>Cor. on E. bank of creek</p> <p>Ascend through dense thicket</p>
80.00	<p>Set a post 4 ft. long 4 ins. sq. 24 ins. in the ground for cor. to secs. 3, 4, 33 & 34 marked</p> <p style="padding-left: 40px;">T 23 S R 3 W S 34 on NE.,</p> <p style="padding-left: 40px;">T 24 S R 3 W S 3 on SE.,</p> <p style="padding-left: 40px;">T 24 S R 3 W S 4 on SW., and</p> <p style="padding-left: 40px;">T 23 S R 3 W S 33 on NW.,</p> <p>faces with 3 notches on E. & W. faces from which</p> <p style="padding-left: 40px;">A spruce, 36 ins. diam., bears S.70*E. 35 lks. dist. marked T 24 S R 3 W S 3 B T</p> <p style="padding-left: 40px;">A spruce, 36 ins. diam., bears S.20*W. 11 lks. dist. marked T 24 S R 3 W S 4 B T</p> <p style="padding-left: 40px;">A fir, 36 ins. diam., bears N.60*W. 5 lks. dist. marked T 23 S R 3 W S 33 B T</p> <p style="padding-left: 40px;">A fir, 40 ins. diam., bears N.10*E. 70 lks. dist. marked T 23 S R 3 W S 34 B T</p> <p>Cor. on slope of mountain in dense hemlock thicket</p> <p>Land mountainous & steep</p>