

County Surveyor's Record, Douglas County, Oregon

Subdivisional Lines of T. 23 S., R. 3 W.

CHAINS

,marked T 23 S R 3 W S 24 B T

No other trees near--Pitts or mounds impracticable--

Land steep and rough

Soil 2nd rate

Densely covered with forest of fir & hemlock timber

80.00 chs.

Thick vine maple underbrush

East, on a random line bet. secs. 24 & 25

Var. 21*E.

30.00 Summit of mountain + 2000 ft. course N. & S.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

63.00 Rock bluff + 30 ft.

77.50 Stream 3 lks. wide flows NE.

79.90 Intersect E. Bdy. of Tp. 10 lks. N. of cor. to secs.

19, 24, 25 & 30 which is

A post 4 ft. long 4 ins. sq. 24 ins. in the ground
marked

T 23 S S 19 on NE.,

R 2 W S 30 on SE.,

R 3 W S 25 on SW., and

S 24 on NW.

faces with 4 notches on North and 2 notches on S. faces
from which

A hemlock, 20 ins. diam., bears N.45*E. 50 lks. dist.

marked T 23 S R 2 W S 19 B T

A hemlock, 8 ins. diam., bears S.45*E. 50 lks. dist.

marked T 23 S R 2 W S 30 B T

A hemlock, 7 ins. diam., bears S.45*W. 40 lks. dist.

marked T 23 S R 3 W S 25 B T

A fir, 50 ins. diam., bears N.40*W. 15 lks. dist.

marked T 23 S R 3 W S 24 B T

Thence, North, 89*56'W. on true line bet. secs. 24 & 25

Var. 19*30'E.