

County Surveyor's Record, Douglas County, Oregon

12

Subdivisional Lines of T 23 S., R. 3 W.

CHAINS	
	<p>A cedar, 24 ins. diam., bears S.65*W. 23 lks. dist. marked T 23 S R 3 W S 23 B T</p> <p>A fir, 24 ins. diam., bears N.35*W. 55 lks. dist. marked T 23 S R 3 W S 14 B T</p> <p>Land steep northern slope of mountain</p> <p>Soil 2nd rate</p> <p>Densely covered with a forest of fir and hemlock timber</p> <p>80.00 chs.</p> <p>Thick underbrush vine maple & rhododendron</p>
	<p>East, on a random line bet. Secs. 13 & 24 Var. 20* 30' E.</p>
11.75	Stream 8 lks. wide flows NE.
28.75	Spring branch 3 lks. wide flows NE.
40.00	Set temp. 1/4 Sec. Cor.
55.50	Summit of Mountain 1000 ft. course N. & S.
80.00	Intersect N. & S. line 50 lks. N. of Cor. to Secs. 13, 18, 19 & 24 which is
	<p>A post 4 ft. long 4 ins. sq. 24 ins. in the ground marked</p> <p>T 23 S S 18 on NE.,</p> <p>R 2 W S 19 on SE.,</p> <p>R 3 W S 24 on SW., and</p> <p>S 13 on NW.,</p> <p>faces with 3 notches on N. & S. edges from which</p> <p>A hemlock, 14 ins. diam., bears N.1*E. 35 lks. dist. marked T 23 S R 2 W S 18 B T</p> <p>A hemlock, 14 ins. diam., bears N.22*W. 25 lks. dist. marked T 23 S R 3 W S 13 B T</p> <p>A cedar, 30 ins. diam., bears S.60*E. 29 lks. dist. marked T 23 S R 2 W S 19 B T</p> <p>A cedar, 20 ins. diam., bears S.25*W. 35 lks. dist. marked T 23 S R 3 W S 24 B T</p> <p>Thence</p>
	<p>N.89* 38' W. On true line bet. Secs. 13 & 24 Var. 19* E.</p>
40.00	A hemlock, 5 ins. diam. which I mark 1/4 on N. side for