

County Surveyor's Record, Douglas County, Oregon

Subdivisional Lines of T. 23 S., R. 3 W.

CHAINS	<p>Densely covered with forest of fir & hemlock timber 80.00 chs.</p> <p>Thick underbrush of vine maple & hemlock</p>
	<p>East, on a random line bet. secs. 23 & 26 Var. 19* E.</p>
15.50	Branch 2 lks. wide flows S.
29.75	Creek 8 lks. wide flows SW.
40.00	Set temp. $\frac{1}{4}$ sec. cor.
51.85	Creek 6 lks. wide flows S.
80.20	Intersect N. & S. line 21 lks. S. of cor. to secs. 23, 24, 25 & 26
	South, 89* 51' W. On true line bet. Secs. 23 & 26
40.10	A chinquapin 4 ins. diam., which I mark $\frac{1}{4}$ S. on N. side for $\frac{1}{4}$ sec. cor. from which A fir, 60 ins. diam., bears S.30*E. 15 lks. dist. marked $\frac{1}{4}$ S B T A fir, 40 ins. diam., bears N.13*W. 55 lks. dist. marked $\frac{1}{4}$ S B T
80.20	Cor. to secs. 22, 23, 26 & 27 Land rough & steep Soil 2nd rate Densely covered with forest of fir, hemlock and cedar timber 80.20 chs. Thick underbrush of fir & hemlock Aug. 7, 1882
	<p>North, bet. secs. 22 & 23 Var. 19* E.</p> <p>Ascend through fir & hemlock thickets</p>
20.00	Summit of mountain course E. & W. + 1500 ft. and de- scend through dense forest of fir
40.00	A hemlock, 10 ins. diam., which I mark $\frac{1}{4}$ S. on W. face for $\frac{1}{4}$ sec. cor. from which A hemlock, 12 ins. diam., bears S.40*E. 10 lks.