

County Surveyor's Record, Douglas County, Oregon

28

 Subdivisional Lines of T. 23 S., R. 3 W.

CHAINS	
80.30	Intersect N. & S. line 21 lks. N. of cor. to secs. 26 & 27, 34 & 35 North, 89°51'W. On true line bet. secs. 27 & 34 Var. 19°E.
40.15	Set a post 3 ft. long 4 ins. sq. 20 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S. on N. face from which A fir, 24 ins. diam., bears S.45°E. 25 lks. dist. marked $\frac{1}{4}$ S B T A fir, 36 ins. diam., bears N.45°E. 4 lks. dist. marked $\frac{1}{4}$ S B T
80.30	Cor. to secs. 27, 28, 33 & 34 Land quite broken Soil 2nd rate Densely covered with a forest of fir & hemlock timber 80,30 chs. Thick fir & cedar underbrush
	North, bet. secs. 27 & 28 Var. 19° 30' E.
11.50	Stream 2 lks. wide flows E. Ascend
28.00	Summit of mountain Course E. & W. + 1000 ft.
38.00	Marsh
39.00	Leave marsh
40.00	A hemlock, 5 ins. diam., which I mark $\frac{1}{4}$ S. on W. side for $\frac{1}{4}$ sec. cor. from which A hemlock, 5 ins. diam., bears E. 18 lks. dist. marked $\frac{1}{4}$ S B T A hemlock, 6 ins. diam., bears W. 30 lks. dist. marked $\frac{1}{4}$ S B T
46.50	Stream 2 lks. wide flows NE.
80.00	Set a post 4 ft. long 4 ins. sq. 24 ins. in the ground for cor. to secs. 21, 22, 27 & 28 marked T 23 S S 22 on NE., R 3 W S 27 on SE.,