

County Surveyor's Record, Douglas County, Oregon

33

Subdivisional Lines of T. 23 S., R. 3 W.

CHAINS

A cedar, 15 ins. diam., bears N.85*W. 20 lks. dist.
marked $\frac{1}{2}$ S B T

A cedar, 12 ins. diam., bears S. 55 lks. dist.
marked $\frac{1}{2}$ S B T

80.00 Cor. to secs. 9, 10, 15 & 16

Land rolling and broken

Soil 2nd rate

Densely covered with forest of fir, hemlock & cedar with
timber 80.00 chs.

Thick vine maple & rhododendron underbrush

North, bet. secs. 9 & 10 on random line

Var. 22* E.

Descend through dense forest of fir

40.00 Set temp. $\frac{1}{2}$ sec. cor.

52.00 Creek 8 lks. wide flows W.

80.55 Intersect E. & W. line 1.40 lks. E. of cor. to secs.
3, 4, 9 & 10 which I find to be

A post firmly set in the ground marked

T 23 S S 3 on NE.,

R 3 W S 10 on SE.,

S 9 on SW., and

S 4 on NW.,

faces with 5 notches on the S. and 3 notches on E. edges
from which

A fir, 16 ins. diam. bears N.41*E. 37 lks. dist.

marked T 23 S R 3 W S 3 B T

A vine maple, 4 ins. diam., bears S.45*E. 13 lks. dist.

marked T 23 S R 3 W S 10 B T

A vine maple, 5 ins. diam., bears S.66*W. 6 lks. dist.

marked T 23 S R 3 W S 9 B T

A maple, 8 ins. diam., bears N.25*W. 17 lks. dist.

marked T 23 S R 3 W S 4 B T

Thence

S.1*E On true line bet. secs. 9 & 10

Var. 19* E.