

County Surveyor's Record, Douglas County, Oregon

45

Subdivisional Lines of T. 23 S., R. 3 W.

CHAINS

North, bet. secs. 29 & 30

Var. 18° 30' E.

19.25 Spring branch 2 lks. wide flows NE.

40.00 A post 4 ft. long 4 ins. sq. 24 ins. in the ground for
 $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S. on W. face from whichA hemlock, 36 ins. diam., bears S. 25 lks. dist.
marked $\frac{1}{4}$ S B TA yew, 7 ins. diam., bears N.30°E. 20 lks. dist.
marked $\frac{1}{4}$ S B T

67.50 Enter creek

71.50 Leave creek and ascend along creek

80.00 A post 4 ft. long 4 ins. sq. 24 ins. in the ground
marked for cor. to secs. 19, 20, 29 & 30 marked

T 23 S S 20 on NE.,

R 3 W S 29 on SE.,

S 30 on the SW. and

S 19 on the NW.

faces with 2 notches on the S. and 5 notches on E.

edges from which

A cedar, 20 ins. diam., bears N.45°E. 37 lks. dist.
marked T 23 S R 3 W S 20 B TA yew, 12 ins. diam., bears S.40°E. 30 lks. dist.
marked T 23 S R 3 W S 29 B TA hemlock, 9 ins. diam., bears S.5°W. 3 lks. dist.
marked T 23 S R 3 W S 30 B TA yew, 6 ins. diam., bears N.10°W. 32 lks. dist.
marked T 23 S R 3 W S 19 B T

Land level or gently rolling

Soil 1st rate

Densely covered with a forest of fir, cedar & hemlock
timber 80.00 chs.

Thick underbrush of vine maple & sallow

East on random line bet. secs. 20 & 29

Var. 19° 30' E.