

## County Surveyor's Record, Douglas County, Oregon

48  
Subdivisional Lines of T. 23 S., R. 3 W.

CHAINS	<p>65.00 Creek 10 lks. wide flows NE.,</p> <p>80.00 Set a post 4 ft. long 3 ins. sq. 24 ins. in the ground for cor. to secs. 17, 18, 19 &amp; 20 marked</p> <p style="padding-left: 40px;">T 23 S S 17 on NE.,</p> <p style="padding-left: 40px;">R 3 W S 20 on SE.,</p> <p style="padding-left: 40px;">S 19 on SW., and</p> <p style="padding-left: 40px;">S 18 on NW.</p> <p>faces with 3 notches on the S. and 5 notches on the E. edges from which</p> <p style="padding-left: 40px;">A yew, 7 ins. diam., bears N.15*E. 4 lks. dist. marked T 23 S R 3 W S 17 B T</p> <p style="padding-left: 40px;">A yew, 6 ins. diam., bears S.20*E. 35 lks. dist. marked T 23 S R 3 W S 20 B T</p> <p style="padding-left: 40px;">A fir, 50 ins. diam., bears S.10*W. 8 lks. dist. marked T 23 S R 3 W S 19 B T</p> <p style="padding-left: 40px;">A fir, 60 ins. diam., bears N.50*W. 10 lks. dist. marked T 23 S R 3 W S 18 B T</p> <p>cor. 1.50 chs. from creek</p> <p>Land very rough &amp; broken</p> <p>Soil 1st &amp; 2nd rate, rocky</p> <p>Densely covered with forest of fir, hemlock &amp; cedar timber 80.00 chs.</p> <p>Thick fir &amp; hemlock underbrush</p>
	<p>East, on random line bet. secs. 17 &amp; 20</p> <p style="text-align: right;">Var. 19* E.</p> <p>1.00 Garroutte Creek 10 lks. wide flows N.</p> <p>36.50 Stream 2 lks. wide flows N.</p> <p>40.00 Set. temp. <math>\frac{1}{4}</math> sec. cor.</p> <p>46.50 Summit of mountain + 1500 ft. course N. &amp; S.</p> <p>66.25 Coast fork river 30 lks. wide flows N.</p> <p>79.70 Intersect N. &amp; S. line 14 lks. N. of cor. to secs. 16, 17, 20 &amp; 21</p> <p style="padding-left: 40px;">N.89*56'W. On true line bet. secs. 17 &amp; 20</p> <p>39/85 Set a basalt stone 12x10x6 ins. 8 ins. in the ground for</p>