

County Surveyor's Record, Douglas County, Oregon

49

 Subdivisional Lines of T. 23 S., R. 3 W.

CHAINS

$\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N. face from which

A cedar, 20 ins. diam., bears S.20*W. 15 lks. dist.
marked $\frac{1}{4}$ S B T

A hemlock, 6 ins. diam., bears N.30*W. 10 lks. dist.
marked $\frac{1}{4}$ S B T

79.70 Cor. to secs. 17, 18, 19 & 20

Land mountainous steep & rough

Soil 1st & 2nd rate

Densely covered with forest of fir & hemlock timber

79.70 chs.

Thick underbrush vine maple

Aug. 18, 1882

West, on random line bet. secs. 18 & 19

Var. 19*E.

4.75 Stream 3 lks. wide flows SE.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

56.50 Stream 6 lks. wide flows E.

76.25 Stream 3 lks. wide flows NE.

80.20 Intersect W. bdy. 30 lks. S. of cor. to secs. 13, 18, 19,
& 24 which is

A vine maple, 6 ins. diam., marked

T 23 S S 18 on NE.,

R 3 W S 19 on SE.,

R 4 W S 24 on SW., and

S 13 on NW.,

faces with 3 notches on N. & S. faces from which

A fir, 48 ins. diam., bears S.50*E. 12 lks. dist.

marked T 23 S R 3 W S 19 B T

A vine maple, 5 ins. diam., bears S.10*W. 30 lks. dist.

marked T 23 S R 4 W S 24 B T

A vine maple, 6 ins. diam., bears N.10*W. 25 lks. dist.

marked T 23 S R 4 W S 13 B T

A fir, 30 ins. diam., bears N.65*E. 33 lks. dist.

marked T 23 S R 3 W S 18 B T

Thence