

County Surveyor's Record, Douglas County, Oregon

51

Subdivisional Lines of T. 23 S., R. 3 W.

CHAINS

marked T 23 S R 3 W S 7 B T

A maple, 6 ins. diam., bears N.15*E. 6 lks. dist.

marked T 23 S R 3 W S 8 B T

A maple, 6 ins. diam., bears S.75*E. 48 lks. dist.

marked T 23 S R 3 W S 17 B T

A yew, 6 ins. diam., bears S.75*W. 8 lks. dist.

marked T 23 S R 3 W S 18 B T

Land rolling and uneven

Soil generally 1st rate

All densely covered with forest of fir, hemlock and
cedar timber 80.00 chs.

Thick vine maple underbrush

East, on random line bet. secs. 8 & 17

Var. 18*15' E.

5.75 Stream 6 lks. wide flows NE.

9.00 Stream 8 lks. wide flows SE.

40.00 Set temp. $\frac{1}{2}$ sec. cor.

52.00 Garoutte Creek 50 lks. wide flows N.

73.00 Stream 3 lks. wide flows NW.

79.65 Intersect N. & S. line 30 lks. N. of cor. to secs. 8, 9,
16 & 17

N.89*47'W. On true line bet. secs. 8 & 17

39.87 Set a post 4 ft. long 3 ins. sq. 24 ins. in the ground
marked $\frac{1}{2}$ on N. face for $\frac{1}{2}$ sec. cor. from which

A fir, 40 ins. diam., bears N. 10 lks. dist.

marked $\frac{1}{2}$ S B T

A fir, 40 ins. diam., bears S.36*E. 30 lks. dist.

marked $\frac{1}{2}$ S B T

79.65 Cor. to secs. 7, 8, 17 & 18

Land rough and broken

Soil 1st & 2nd rate

Densely covered with forest of fir, hemlock and cedar
timber 79.65 chs.

Thick underbrush of vine maple and sallow

Aug. 19, 1882