

County Surveyor's Record, Douglas County, Oregon

52

Subdivisional Lines of T. 23 S., R. 3 W.

CHAINS	West, on random line bet. Secs. 7 & 18 Var. 18*15' E.
8.50	Stream 4 lks. wide flows SE.
17.30	Stream 5 lks. wide flows E.
40.00	Set temp. $\frac{1}{4}$ sec. cor.
49.50	Stream 6 lks. wide flows NE.
72.00	Summit of Calapooia mountains + 2000 ft.
79.75	Intersect W. bdy. of Tp. 60 lks. S. of cor. to Secs. 7, 12, 13 & 18 which is
	A post firmly set in the ground marked
	T 23 S S 7 on NE.,
	R 3 W S 18 on SE.,
	R 4 W S 13 on SW.,
	S 12 on NW.
	faces with 2 notches on the N. and 4 notches on the S. faces from which
	A cedar, 15 ins. diam., bears N.50*W. 45 lks. dist. marked T 23 S R 4 W S 12 B T
	A cedar, 8 ins. diam., bears S.68*W. 37 lks. dist. marked T 23 S R 4 W S 13 B T
	A cedar, 12 ins. diam., bears S.55*E. 12 lks. dist. marked T 23 S R 3 W S 18 B T
	A fir, 80 ins. diam., bears N.50*E. 19 lks. dist. marked T 23 S R 3 W S 7 B T
	Thence
	S.89*34' E. On true line bet. secs. 7 & 18
	Var. 18*30'E.
39.75	A vine maple 8 ins. diam., which I marked $\frac{1}{4}$ S. on N. face for $\frac{1}{4}$ sec. cor. from which
	A maple, 5 ins. diam., bears N.60*W. 6 lks. dist. marked $\frac{1}{4}$ S B T
	A hemlock, 6 ins. diam., bears S.8*E. 10 lks. dist. marked $\frac{1}{4}$ S B T
79.75	Cor. to secs. 7, 8, 17 & 18
	Land broken & rolling
	Soil 1st rate