

35
County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 23 S., R. 4 W.,
As surveyed by William P. Wright, deputy Surveyor
Under Contract No. 514, dated August 27, 1884

CHAINS

Finding it impracticable to extend the South boundary E of sec. 35 & 36 on account of the precipitous character of the face of the country and impossible to run N between secs. 34 & 35 for the same reason I start from the cor. to secs. 27, 28, 33 & 34, which corner I found a post 4 ins. in ground marked T 23 S R 4 W S 27 on NE, S 34 on SE, S 33 on SW, S 28* NW, face from which

A fir, 6 ins. diam., bears S.18*W., 11 lks. dist.

Marked T 23 S R 4 W S 33 B T

A fir, 4 ins. diam., bears S.60*E., 43 lks. dist.

Marked T 23 S R 4 W S 34 B T

A maple, 8 ins. diam., bears N.67*E., 10 lks. dist.

Marked T 23 S R 4 W S 27 B T

A fir, 3 ins. diam., bears N.46*W., 8 lks. dist.

Marked T 23 S R 4 W S 28 B T

Thence I run East on true line between secs. 27 & 34

Va.19*E

Descend 27* slope

9.50 Branch 2 lks. wide, flows SW ascend 30*

28.00 Descend 15*

30.75 Ascend 22*

40.00 Set post 4 ins. diam. 4 ft. long with marked stone 12 ins. in ground for $\frac{1}{4}$ sec. cor. sec. marked $\frac{1}{4}$ S on N face from which

A chinquapin, 12 ins. diam., bears N.87*E., 55 lks. dist.

A fir, 40 ins. diam., bears N.67*E., 82 lks. dist.

43.00 Descend 25*

47.80 Ascend 10*

52.00 Descend 22*

73.80 Branch 2 lks. wide flows SW ascend 15*

80.00 Set post 6 ins. diam., 4 ft. long with marked stone 12 in. in ground for cor. to secs. 26, 27, 34 & 35

Marked T 23 S S 26 on NE, R 4 W S 35 on SE,