

44
County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 23 S., R. 4 W.

CHAINS	
	<p>Land rough, mountainous Soil, poor & thin Dense fir and cedar timber Thick undergrowth of hazel 80 chs.</p> <p style="text-align: right;">November 1st</p>
	<p>East, on random line between sec. 23 & 26 Va. 19*E</p>
40.00	Set temp. $\frac{1}{4}$ sec. cor.
79.50	Intersect N & S line 42 lks. N of cor. to sec. 23, 24, 25 & 26 Thence I run N.89*42*W on true line between Sec. 23 & 26 Descend 20*
24.00	Branch flows SW 2 lks. wide ascend 27*
39.75	Set post 4 ins. diam., 4 ft. long with marked stone 12 ins. in ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on N face from which A fir, 36 ins. diam., bears N.28*E, 33 lks. dist. Marked $\frac{1}{4}$ S B T A fir, 40 ins. diam., bears S.12*E., 18 lks. dist. Marked $\frac{1}{4}$ S B T Descend 14*
51.00	Branch 8 lks. flows NW ascend 21*
79.50	The cor. to sec. 22, 23, 26 & 27 Land, rough, mountainous Soil, poor, thin, rocky Dense fir timber, poor quality Thick undergrowth of hazel 79.50
	<p>West on random line between sec. 22 & 27 Va. 20*E</p>
40.00	Set temp. $\frac{1}{4}$ sec. cor.
80.30	Intersect N & S line 70 lks. south of cor. to Sec. 21, 22, 27 & 28, which is a post 4 ins. diam., 4 ft. long in ground marked T 23 S S 22 on NE, R 4 W S 27 on SE,