

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 23 S., R. 4 W.,

CHAINS	
	East on random line between Sec. 17 & 20 Va. 20*E
40.00	Set temp. $\frac{1}{4}$ sec. cor.
80.10	Intersect N & S line 10 lks. North of cor. to sec. 16, 17, 20 & 21 which is a post 4 ins. diam., in ground marked T 23 S S 16 on NE, R 4 W S 21 on SE, S 20 on SW, S 17 on NW face with 4 notches in E and 3 on S edge, from which A fir, 15 ins. diam., bears S.60*E., 34 lks. dist. Marked T 23 S R 4 W, S 21 B T A fir, 30 ins. diam., bears N.76*W., 37 lks. dist. Marked T 23 S R 4 W, S 16 B T N.89*56'W on true line between Sec. 17 & 20 Ascend mountain 20*
25.00	Ascend 27*
40.05	Top of ridge set post 4 ins. diam., 4 ft. long with marked stone 12 ins. in ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on N face, from which A fir, 36 ins. diam., bears N.75*E., 60 lks. dist. Marked $\frac{1}{4}$ S B T A fir, 24 ins. diam., bears N.64*W., 31 lks. dist. Marked $\frac{1}{4}$ S B T Descend 25*
75.00	Branch 1 lk. wide flows SW ascend
80.10	The cor. to sec. 17 & 18, 19 & 20 Land, rough & mountainous Soil, 2nd rate Dense fir and cedar timber Thick undergrowth of hazel 80.10 chs. November 2, 1884