

County Surveyor's Record, Douglas County, Oregon

Sub-divisions of T 23 S., R. 4 W.,

CHAINS

in ground marked T 23 S S 7 in NE, R 4 W S 18 on SE,
R 5 W S 13 on SW, S 12 on N W face from which

A cedar, 8 ins. diam., bears S.84*W., 19 lks. dist.

Marked T 23 S R 5 W, S 13 B T

A fir, 12 ins. diam., bears N.65*W., 41 lks. dist.

Marked T 23 S R 5 W, S 13 B T

A fir, 12 ins. diam., bears N.20*E., 25 lks. dist.

Marked T 23 S R 4 W, S 7 B T

A fir, 12 ins. diam., bears S.69*E., 38 lks. dist.

Marked T 23 S R 4 W, S 18 B T

Thence I run N.89*49'E on true line between Sec. 7 & 18

Descend 15*

30.00 Branch 4 lks. wide flows NW Ascend 37*

34.00 Descend 29*

36.00 Branch 1 lk. flows N W ascend 20*

39.90 Set post 4 ins. diam., 4 ft. long with marked stone 12
ins. in ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on N face
from which

A fir, 6 ins. diam., bears S.66*W., 16 lks. dist.

Marked $\frac{1}{4}$ S B T

A fir, 40 ins. diam., bears N.35*W., 120 lks. dist.

Marked $\frac{1}{4}$ S B T

51.00 Descend 29*

61.50 Branch 2 lks. wide flows NW

66.00 Branch 4 lks. wide flows NW

70.00 Branch 1 lk. wide flows NW

79.80 The cor. to sec. 7, 8, 17 & 18

Land mountainous & rough

Soil 2nd rate

Timber fir and cedar

Thick undergrowth of hazel 79.80