

Subdivisions of T. 23 S., R. 4 W.,

CHAINS

General Description

The South and East line of sections run West. Mostly high precipitus mountains of the Calapooia range of mountains in Sections 7, 8, 18, 17, 19 & 20. The mountains not so high nor so steep in places. Fit for cultivation. The timber most all over the section Surveyed is of good quality. Soil with but little exception of 3rd rate quality.

Retracement of North Boundary of Sec. 3,
T. 24 S., R. 4 W., as executed by Oscar F. Thiel,
Deputy Surveyor, under Contract No. 658, dated
May 21, 1896

Thence I run S.89°58'W on true line between secs. 3 & 34 over rough ground, covered with heavily fir timber and a dense undergrowth of hazels and small fir timber.

- .50 Leave top of ridge bears N & S begin to descend
- 9.50 A dry gulch, course N, 80 ft. below ridge ^A descend again.
- 24.50 Top of ridge, bears NW & SE; 50 ft. above gulch begin to descend
- 39.91 Qr. sec. cor, which is a hemlock post, 3 ins. sq., 24 ins. above ground, marked and witnessed as described by the surveyor general.
- 58.40 A road, bears N & S
- 65.00 A branch 15 lks. wide, course N.30°W. 150 ft. below $\frac{1}{4}$ sec. cor.
- 75.40 A stream 2 lks. wide, course NE
- 77.68 The cor. of secs. 3, 4, 33 and 34

Clouds prevented the taking of latitude.

Land mountainous

Soil gravelly, 3rd rate

Timber, fir, cedar, hemlock, maple

Mountainous or heavily timbered land 77.68 chs.

September 16, 1897