

County Surveyor's Record, Douglas County, Oregon

South boundary of T. 23 S., R. 4 W.

CHAINS

Marked T 23 S R 4 W S 34 B T.

No other trees within limits; raised a mound of stone
2 ft. base, 1½ ft. high, W of cor.

July 16

Land, mountainous

Soil, 4th rate

Timber, fir, hemlock, cedar, chinquin, madrona, maple,
and dogwood

Dense undergrowth of maple, mountain-balm, ocean-spray,
hazel, and salal-berry.

Mountainous land or covered with dense undergrowth 40 chs.

Thence I run East, on random line, setting temporary ¼
sec. and sec. cors. at intervals of 40.00 chs., along
the S bdy. of T. 23 S., R. 4 W., and, at 160.15 chs.
Intersect the W Bdy. of T. 23 S., R. 3 W., 4.71 chs.
N of the cor. of T. 23 and 24 S., Rs. 3 and 4 W, which
is a sandstone 12x8x6 ins. in mound of stone, marked
and witnessed as described by the surveyor general.

This cor. I reestablish as follows: Set a sandstone,
12x8x6 ins. in mound of stone, for SW cor. of T. 23
S., R. 3 W., marked with 6 notches on N and E edges;
from which

A cedar, 36 ins. diam., bears N.1°E., 75 lks. dist.

Marked T 23 S R 3 W S 31 B T

Excavation impracticable. I destroy all other access-
ories to this cor. At the point of intersection, 4.71
chains N of this cor. Set a hemlock post 3 ft. long,
4 ins. sq. 24 ins. in the ground, for closing corner
of T 23 and 24 S, R 4 W, marked C C R 4 W on W, T 23
S S 36 on N, and T 24 S S 1 on S faces with 6
grooves on the N, S, and W faces, from which

A hemlock, 16 ins. diam., bears N.16°W., 9 lks. dist.

Marked T 23 S R 4 W S 36 B T

A hemlock, 20 ins. diam., bears S.40°W., 52 lks.

dist. Marked T 24 S R 4 W S 1 B T