

South Boundary of T. 23 S., R. 4 W.

CHAINS

General description

The south boundary of this township lies in an extremely rough and mountainous country, covered with a dense undergrowth of vine-maple, mountain-balm, rhododendron and hazel. There is some good timber in section 35, but difficult of access. These parts are well watered by clear mountain streams.

Carl S. Nicklin,

U. S. Deputy Surveyor

July 17, 1897

Subdivisions of T. 23 S., R. 4 W.  
As surveyed by Carl S. Nicklin, Deputy Surveyor, under  
Contract No. 664 Dated May 23, 1896

21.38

I begin at the witness post, described, "as on a line run S. bet. secs. 34 & 35, at 62.50 chs.", which is a post 20 ins. above ground, marked and witnessed as described by the surveyor general.

Thence I run south on random line, bet. secs. 34 & 35

Intersect E and W line, 96 lks. E of cor. of secs. 2, 3, 34 and 35 which I reestablished July 16, 1897.

The falling being greater than the required limit for closing. I obliterate all marks on the bearing tree in sec. 34 and remove mound of stone; and, at point of intersection, 96 lks. E of this cor., I set a basalt stone, 16x12x8 ins. 10 ins. in the ground for closing cor. of secs. 34 and 35, marked C C on N, with 2 grooves on E and 4 grooves on W faces; from which

A madrona, 12 ins. diam., bears N.78°E., 63 lks. dist.

Marked T 23 S R 4 W S 35 B T

A madrona, 8 ins. diam., bears N.65°W., 147 lks. dist.

Marked T 23 S R 4 W S 34 B T

This cor. is on a steep hillside sloping S

Mag. Decl. 19°30'E

Thence I run North, on a true line, bet. secs. 34 & 35

ascend spur