

Subdivision of T. 23 S., R. 6 W., W.M.
As surveyed by Wm. Thiel, Deputy Surveyor, under
Contract No. 310, dated November 30th, 1878.

CHAINS

	Commence at the post to corner of secs. 1 and 2, Tp. 24 S., and secs. 35 and 36, Tp. 23 S., R. 6 West, from which	
	A Laurel, 14 ins. diam., bears N.74 $\frac{1}{2}$ *E., 100 lks.	
	A Fir, 36 ins. diam., bears S.60*E., 98 lks., (Is now down)	
	A Fir, 50 ins. diam., bears S.78*W., 64 lks.	
	A Fir, 12 ins. diam., bears N.73*W., 124 lks.	
	In accordance with the field notes furnished by your office, I run thence;	
	North on line between secs. 35 and 36	
		Va. 19*25'E.
		Latitude- 43*32'N.
4.75	Top of steep Spur, course East	+70
	West, commence descent	
9.40	Top of Spur, course SE & NW	-50
	Still descending	
15.70	Canyon, course East	-120
	Commence ascending	
19.25	Top of Spur, course SE & NW	+180
	Commence descending	
26.50	Canyon, course East	-150
	Commence ascent	
33.90	A Fir, 30 ins. Diam.	
38.00	Leave Timber	
40.00	Set $\frac{1}{2}$ sec. post alongside of a boulder, 48" x 42",	+60
	from which	
	A Fir 30 ins. diam., bears S.3 $\frac{1}{2}$ *E., 63 lks.	
	A Laurel 4 ins. diam., bears S.89 $\frac{1}{2}$ *W., 33 lks.	
43.50	Top of Bald spur, commence descent	+20
44.00	Enter timberflat.	-20
52.50	Commence ascent	+20
58.50	Canyon, course E., commence ascending a very steep hill.	-10