

Subdivision of T 23 S., R. 6 W.

CHAINS	<p>From which</p> <p>A Fir, 48 ins. diam., bears N.40*E., 113 lks. dist Marked T 23 S R 6 W S 13 B T</p> <p>A Fir, 24 ins. diam., bears S.82*E., 15 lks. dist. Marked T 23 S R 6 W S 24 B T</p> <p>A Fir, 30 ins. diam., bears S.52*W., 49,lks. dist. Marked T 23 S R 6 W S 23 B T</p>
--------	---

The partially completed dependant resurvey of T. 23 S., R. 6 W. was made by Mr. Gould just before he was transferred from field to office, he has therefore, furnished me with the following statement:

"The preliminary retracements of part of T. 23 S., R. 6 W., W. M., Oregon were made in 1943 by Otis O. Gould. Before he left in the fall corners were established around sections 1, 2, 11, 12, 13 and 36. This survey is not approved and is unofficial. $\frac{1}{4}$ sec. and section corners were left at the temporary points on most of the east half of the township, none that are not set were at old corners. Since Mr. Gould left the field the old $\frac{1}{4}$ sec. cor. of secs. 13 and 14 has been found about 2 or 3 chains S. and a little to the west of where the $\frac{1}{4}$ sec. cor. was proportioned in and established."

(Quoted from a letter from Geo. F. Rigby to Ben B. Irving, County Surveyor, dated December 29, 1954.)

	<p>East on random line bet. Sec. 13 & 24.</p> <p style="text-align: right;">Va. $19\frac{1}{8}$*E.</p> <p>Through Timber.</p>
7.20	A hemlock, 20 ins. diam.
13.25	A Brook, 2 lks. wide, course NW.
35.52	A Fir, 30 ins. diam.
36.00	A Ridge, course NW & SE
40.00	Set temporary $\frac{1}{4}$ sec. cor.
52.90	A Hemlock, 20 ins. diam.
80.35	<p>Intersect East Boundary of T. 24 lks. N. of the cor. to Secs. 13, 24, 18 and 19, which is a post firmly set in the ground, 4 in. sq.,</p> <p style="text-align: center;">Marked T 23 S S 18 on NE., R 5 W S 19 on SE., R 6 W S 24 on SW., S 13 on NW face, with 3 notches on N & S edges, from which</p> <p>A Fir, 16 ins. diam., bears N.82*W., 25 lks. dist Marked T 23 S R 6 W S 13 B T</p>

+500