

Subdivision of T 23 S., R. 6 W.

CHAINS

From which

A Fir, 48 ins. diam., bears N.40*E., 113 lks. dist

Marked T 23 S R 6 W S 13 B T

A Fir, 24 ins. diam., bears S.82*E., 15 lks. dist.

Marked T 23 S R 6 W S 24 B T

A Fir, 30 ins. diam., bears S.52*W., 49,lks. dist.

Marked T 23 S R 6 W S 23 B T

A Fir 16 ins. diam., bears N.55*W., 40 lks. dist.

Marked T 23 S R 6 W S 14 B T

Land, mountainous.

Soil, 2nd rate.

Timber, Densely covered with forest of pine, fir, cedar, hemlock, laurel, chincapin and dogwood.

Undergrowth, thick with vine, maple, sallah, manzanito, fir and huckleberry.

June 13th, 1883

East on random line bet. Sec. 13 & 24.

Va. 19 $\frac{1}{2}$ *E.

Through Timber.

7.20 A hemlock, 20 ins. diam.

13.25 A Brook, 2 lks. wide, course NW.

35.52 A Fir, 30 ins. diam.

36.00 A Ridge, course NW & SE

40.00 Set temporary $\frac{1}{4}$ sec. cor.

52.90 A Hemlock, 20 ins. diam.

80.35 Intersect East Boundary of T. 24 lks. N. of the cor. to Secs. 13, 24, 18 and 19, which is a post firmly set in the ground, 4 in. sq.,

Marked T 23 S S 18 on NE., R 5 W S 19 on SE.,

R 6 W S 24 on SW., S 13 on NW face, with 3 notches on N & S edges, from which

A Fir, 16 ins. diam., bears N.82*W., 25 lks. dist

Marked T 23 S R 6 W S 13 B T

+500