

Subdivision of T 23 S., R 6 W.

CHAINS 80.39	<p>Intersect East Boundary 28 lks. S. of the corner to Secs. 12, 13, 7 and 18, which is a post firmly set in the ground 4 in. sq.,</p> <p>Marked T 23 S S 7 on NE., R 5 W S 18 on SE., R 6 W S 13 on SW., S 12 on NW face with 2 notches on N and 4 notches on S faces, from which</p> <p>A Fir, 30 ins. diam., bears S.61*E., 37 lks. dist</p> <p>Marked T 23 S R 5 W S 18 B T</p> <p>A Fir, 15 ins. diam., bears N.33*E., 37 lks. dist.</p> <p>Marked T 23 S R 5 W S 7 B T</p> <p>A Fir, 24 ins. diam. bears N.50*W, 45 lks. dist.</p> <p>Marked T 23 S R 6 W S 12 B T</p> <p>A Fir, 14 ins. diam., bears S.52½*W., 28 lks. dist.</p> <p>Marked T 23 S R 6 W S 13 B T</p>
40.20	<p>Thence I run S. 89*48'W., on a true line bet. Secs.12& 13.</p> <p>Set a cedar post 3 ft. long, 3 ins. sq., 24 ins. in the ground for ¼ Sec. cor., marked ¼ S. on the N. face, from which</p> <p>A Fir, 20 ins. diam., bears N.13*W., 22 lks. dist.</p> <p>Marked ¼ S B T</p> <p>A Hemlock 8 ins. diam., bears S.25*W., 15 lks. dist.</p> <p>Marked ¼ S B T</p>
80.39	<p>The cor. to secs. 11, 12, 13 & 14.</p> <p>Land mountainous.</p> <p>Soil, 3rd rate.</p> <p>Timber, densely covered with forest of pine, fir, cedar, hemlock, maple, laurel and dogwood.</p> <p>Undergrowth of thick vine maple, laurel and huckleberry, sallal and hazel.</p>
	<p>North bet. Secs. 11 & 12.</p> <p style="text-align: right;">Va. 19½*E.</p>
	<p>Through heavy timber.</p>
10.82	<p>A Cedar, 20 ins. diam.</p>
31.10	<p>A Brook, 4 lks. wide, course N10*W.</p>