

County Surveyor's Record, Douglas County, Oregon

Meanders of T. 23 S., R. 7 W., W. M.

CHAINS

Thence in Sec. 27.

Va. 19*30'E.

N.83*E. 15.00
 N.87*E. 30.25
 N.76*E. 20.50
 N.52*E. 19.00

To cor. to fractional secs. 26
 & 27.

Steep rugged cliffs on last sta-
 tion.

Thence in Sec. 22.

As sec. 26 & 23 are not surveyed on the right bank of
 the river I do not meander those secs, I now commence
 at the corner to fractional secs. 22 & 23.

Va. 19*30'E.

N.70*W. 10.75
 N.81*W. 10.50
 West 19.50
 S.55*W. 7.00
 S.60*W. 9.00
 West 8.00
 N.50*W. 8.08
 N.35*W. 7.50
 N.20*W. 7.25
 N.10*W. 7.50
 N.4*30'W. 17.70

High rocky cliff.

Rapid current in river.

To cor. to fractional secs. 22
 & 15.

Rocky hill on right.

Thence in sec. 15.

Va. 19*30'E.

N.21*45'W. 8.09

To the cor. to fractional sec.
 15 & 16.

Land level. fir timber.