

## Meanders of T. 23 S., R. 7 W., W. M.

CHAINS

N.85\*E. . 7.50

N.64\*E. . 19.25 To the cor. to fractional secs.  
14 & 15., on right bank. As  
secs. 11 & 14 are not surveyed  
I do not meander the right bank  
in those sections.

Now in sec. 10 beginning at the  
cor. to fractional secs. 10 & 11  
on right bank thence in sec. 10.

Va. 19\*30'E.

N.63\*W. . 18.00

S.81\*W. . 22.81

S.62\*W. . 20.50

N.88\*30'W. . 23.60

To the cor. to fractional secs.  
9 & 10.  
Rocky cliff on the right.

Thence in sec. 9.

Va. 19\*30'E.

N.36\*W. . 27.00

N.25\*W. . 8.25

To the cor. to fractional secs.  
4 & 9.

Thence in sec. 4.

Va. 19\*30'E.

N.9\*W. . 10.00

N.2\*W. . 14.00

At 13.00 chs. a brook 4 lks. wide  
enters from the N E.

N.27\*30'W. . 30.00

N.71\*W. . 18.00

A brook 4 lks. wide, from the N E.

S. 81\*W. . 10.50

S.52\*W. . 12.50