

## County Surveyor's Record, Douglas County, Oregon

-60-

South Boundary of T. 23 S., R. 7 W., W. M. as surveyed  
by W. H. Byars, Deputy Surveyor, under Contract #376.  
dated January 22, 1881.

CHAINS	
	<p>Begin at the established cor. to secs. 34 &amp; 35 on South boundary of T. 23 S., R. 7 W., Witness trees all standing and agree with the description furnished by the office viz:</p> <p style="padding-left: 40px;">A black oak, 10 ins. diam., bears S.17°E., 9 lks. dist.</p> <p style="padding-left: 40px;">A black oak, 8 ins. diam., bears S.5°W., 10 lks. dist.</p> <p style="padding-left: 40px;">A white oak, 9 ins. diam., bears N.17°W., 16 lks. dist.</p> <p style="padding-left: 40px;">A white oak, 5 ins. diam., bears N.28°E., 35 lks. dist.</p> <p>East on South boundary of Sec. 35.</p> <p style="text-align: right;">Va. 19°30'E.</p>
2.50	Begin steep descent.
5.00	Rocky bluff, course N & S.
31.00	Creek 5 lks. wide, course SW.
40.00	<p>Set a fir post for the <math>\frac{1}{2}</math> sec. cor., from which,</p> <p style="padding-left: 40px;">A chinquapin, 6 ins. diam., bears N.45°E., 7 lks. dist.</p> <p style="padding-left: 40px;">A fir, 24 ins. diam., bears S.70°E., 66 lks. dist.</p>
46.00	Steep ascent.
50.00	Gentle ascent.
80.00	<p>Set a hemlock post for the cor. to secs. 35 &amp; 36, from which,</p> <p style="padding-left: 40px;">A fir, 16 ins. diam., bears N.42°W., 63 lks. dist.</p> <p style="padding-left: 40px;">A <sup>white</sup> fir, 14 ins. diam., bears N.51°E., 71 lks. dist.</p> <p>Land broken, mountainous, heavily timbered, 3rd rate.</p> <p>Timber chiefly fir, cedar, hemlock, oak, laurel, maple, alder etc.</p>
	<p>East on South boundary of sec. 36.</p> <p style="text-align: right;">Va. 19°30'E.</p>
32.50	Spring, course SW.