

County Surveyor's Record, Douglas County, Oregon

27

South Boundary of T. 23 S., R. 8 W., W. M.

CHAINS	
	<p>T 23 S R 8 W on N</p> <p>S 32 on E and</p> <p>S 31 on W edges with 5 notches on E and 1 notch on W edges from which</p> <p>A hemlock, 20 ins. diam., bears N.55*E., 45 lks. dist., marked T 23 S R 8 W S 32 B T.</p> <p>A hemlock, 5 ins. diam., bears N.20*W., 3 lks. dist., marked T 23 S R 8 W S 31 B T.</p> <p>A hemlock, 24 ins. diam., bears S.18*E., 55 lks. dist., marked T 23 S R 8 W S 31 & 32 B T.</p> <p>Land mountainous 80 chs. Soil 3rd rate. Heavily timbered with hemlock, fir and cedar. Dense undergrowth of hemlock and rhododendron 80.00 chs.</p>
	<p>Thence West on a true line on South boundary of Sec. 31.</p> <p style="text-align: right;">Va. 20*35'E.</p>
.76	Cor. to sec. 5 & 6, T. 24 S., R. 8 W.
11.00	Top of a ridge, course N W., about 100 ft. above Sec. corner. Descend.
33.75	Stream 1 lk. wide, course N W., about 250 ft. below top of last ridge. Ascend gradually.
40.00	Set a post 3 ft. long and 3 ins. sq., 2 ft in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on North face, from which
	A fir, 28 ins. diam., bears N.23*W., 6 lks. dist., marked $\frac{1}{4}$ S B T.
	A hemlock, 6 ins. diam., bears S.70 $\frac{1}{2}$ *W., 32 lks. dist., marked $\frac{1}{4}$ S B T.
40.50	$\frac{1}{4}$ sec. cor. on N boundary of Sec. 6 T. 24 S., R. 8 W.
41.00	Top of a ridge, course N.80*W.
55.00	Descend abruptly over North slope.
59.98	Closing corner to T. 24 S., R. 8 W.
83.47	Hemlock 12 ins. diam., marked with 2 notches on E & W sides.