

County Surveyor's Record, Douglas County, Oregon

-27-

South Boundary of T. 23 S., R. 8 W., W. M.

CHAINS 91.30	A hemlock, 8 ins. diam., marked with 2 notches on E & W sides.
95.00	Top of little spur, course N W.
97.09	A point about 1000 ft. below beginning of last descent, and the closing corner of T. 23 S., R. 8 W. Land 97.09 chs. mountainous. Soil 3rd & 4th rate. Heavily timbered with hemlock, fir and alder. Dense undergrowth of hemlock, sallal, huckleberry and rhododendron. 97.09 chs. <p style="text-align: right;">May 26, 1894.</p>
	Subdivision of T. 23 S., R. 8 W., W. M. Same Deputy and Contract.
40.00	<p>I commence at the cor. to secs. 35 & 36 on the South boundary of the township, at 8 A. M. April 19th.</p> <p>The magnetic bearing of the South boundary of Sec. 36 is N.69°20'E., and after allowing 4' for diurnal change, (as per table on page 550 of the manual), I find the mean declination to be 20°36'E.</p> <p>From this cor. I run N0°1'W., on a random line between Sec. 35 & 36.</p> <p style="text-align: right;">Va. 20°40'E.</p>
80.05	<p>Set a temporary $\frac{1}{4}$ sec. cor.</p> <p>Intersect E & W section line 33 lks. E. of cor. to secs. 25, 26, 35, & 36. which is a post 4 ins. sq., marked</p> <p style="padding-left: 40px;">T 23 S S 25 on N E</p> <p style="padding-left: 40px;">R 8 W S 36 on S E</p> <p style="padding-left: 40px;">S 35 on S W and</p> <p style="padding-left: 40px;">S 26 on N W faces with 1 notch on S & E edges</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 14 ins. diam., bears N.62°E., 35 lks. dist., marked T 23 S R 8 W S 25 B T.</p> <p style="padding-left: 40px;">A fir, 12 ins. diam., bears S.5°E., 11 lks. dist., marked T 23 S R 8 W S 36 B T.</p>