

County Surveyor's Record, Douglas County, Oregon

33

Subdivision of T. 23 S., R. 8 W., W. M.

CHAINS	
	<p>No tree in limits N W of Cor.</p> <p>Pit impracticable.</p> <p>Thence I run ⁵W.0*7'W., on a true line between secs. 13 & 14.</p> <p style="text-align: right;">Va. 20*37'E.</p> <p>Ascend through timber.</p>
41.17	<p>A point about 700 ft. above cor. and set a stone 18 x 14 x 10 ins., 14 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on N face from which</p> <p style="padding-left: 40px;">A laurel, 20 ins. diam., bears S.65*E., 9 lks. dist., marked $\frac{1}{4}$ S B T.</p> <p style="padding-left: 40px;">A fir, 20 ins. diam., bears S.79*W., 65 lks. dist., marked $\frac{1}{4}$ S B T.</p>
41.50	Summit of mountain, course E & W and descend.
51.20	Dry creek bed 2 lks. wide, course S.20*E.
56.20	Same, 2 lks. wide, course S W.
67.00	Top of a ridge, course S W.
81.17	<p>A point 700 ft. below top of mountain at 41.50 chs. on this line. The cor. to secs. 13, 14, 23, & 24.</p> <p>Land mountainous 81.17 chs. Soil 3rd & 4th rate. Heavily timbered with fir, cedar and laurel, with a dense undergrowth of hazel, sallow and briars.</p> <p style="text-align: right;">April 21st, 1894.</p>
	<p>Beginning at the cor. to secs. 34 & 35 on the south boundary of the township, I run</p> <p>N.0*2'W., between secs. 34 & 35.</p> <p style="text-align: right;">Va. 20*50'E., at 8 A M April 24th.</p> <p>Ascend through timber.</p>
8.00	Top of a ridge, course S W.
13.00	Top of a mountain, course E & W., and descend abruptly.
19.79	A cedar, 20 ins. diam., marked with 2 notches on N & S sides.

here