

County Surveyor's Record, Douglas County, Oregon

34

Subdivision of T. 23 S., R. 8 W., W. M.

CHAINS	<p>Land 72.80 chs. mountainous. Soil 3rd & 4th rate. 7.20 chs. level bottom soil 1st rate. Heavily timbered with fir, cedar, alder & maple. Dense undergrowth of hazel, salmonberry, sallal, vine maple and briars. 80 chs.</p>
40.00	<p>N.89°51'E., on a random line between secs, 14 & 23. Va. 20°35'E.</p>
79.56	<p>Set temporary $\frac{1}{4}$ sec. cor. Intersect N & S line 26 lks. S. of cor. to secs. 13, 14, 23 & 24. Thence I run, S. 89°40'W., on a true line between secs. 14 & 23. Va. 20°35'E.</p>
5.00	<p>Over S. slope ascending through timber.</p>
20.00	<p>Top of a spur, course S. descend.</p>
20.00	<p>Stream 1 lk. wide, course S. A point about 300 ft. below top of last spur and ascend.</p>
33.00	<p>Top of a spur, course S. about 200 ft. high and descend.</p>
39.78	<p>Set a post 3 ft. long, 3 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on N. face from which A fir, 12 ins. diam., bears N.64°E., 14 lks. dist., marked $\frac{1}{4}$ S B T. A laurel, 8 ins. diam., bears S.72°E., 49 lks. dist., marked $\frac{1}{4}$ S-B T.</p>
44.00	<p>Stream 1 lk. wide, course S. about 200 ft. below top of last ridge, and ascend.</p>
52.00	<p>Top of a spur, course S., about 200 ft. high.</p>
60.25	<p>Top of a spur, course South.</p>
67.70	<p>Stream 1 lk. wide, course S., a point about 200 ft. below top of last spur and ascend.</p>