

## County Surveyor's Record, Douglas County, Oregon

-57-

## Subdivision of T. 23 S., R. 8 W., W. M.

CHAINS	Land 80 chs. mountainous; soil 3rd & 4th rate. Heavily timbered with fir, hemlock and cedar. Dense undergrowth of vine maple, hazel, sallow, salmonberry and briars.
40.00	East on a random line between Sec. 28 & 33. Va. 20*35'E.
80.72	Set temporary $\frac{1}{2}$ sec. cor. Intersect N & S line 23 lks. S. of cor. to secs. 27, 28, 33 & 34. Thence S.89*50'W., on true line between secs. 28 & 33. Va. 20*42'E.
3.00	Ascend. Top of ridge, course N.10'E., descend.
25.06	Stream 1 lk. wide, course S.70*W., about 250 ft. below top of ridge.
27.00	Stream 4 lks. wide, course N.30*W.
40.36	Set a sandstone 14 x 10 x 5 ins., 10 ins. in the ground for $\frac{1}{2}$ sec. cor. marked $\frac{1}{2}$ on W. face, from which, A hemlock, 10 ins. diam., bears N.19'E., 6 lks. dist., marked $\frac{1}{2}$ S B T. A cedar, 30 ins. diam., bears S.75'E., 13 lks. dist., marked $\frac{1}{2}$ S B T.
41.25	Stream 1 lk. wide, course N.10*W.
56.82	Stream 5 lks. wide, course S W. Ascend.
63.20	Top of a spur, course S. Descend.
73.00	Stream 6 lks. wide, course N.70*W. A point about 250 ft. below top of spur. Ascend
80.72	The cor. of Sec. 28, 29, 32 & 33. Land mountainous 80.72 chs. Soil 3rd & 4th rate. Heavily timbered with fir, cedar and hemlock. Dense undergrowth of vinemaple, sallow and briars 80.72 chs. May 9th, 1894.