

## County Surveyor's Record, Douglas County, Oregon

-59-

Subdivision of T. 23 S., R. 8 W., W. M.

CHAINS

A hemlock, 10 ins. diam., bears S.23\*W., 17 lks. dist., marked T 23 S R 8 W S 29 B T.

A fir, 60 ins. diam., bears N.76\*W., 69 lks. dist., marked T 23 S R 8 W S 20 B T.

Land 80.00 chs. mountainous. Soil 3rd & 4th rate.

heavily timbered with fir, hemlock, maple and cedar.

Dense underbrush of rhododendron, sallow and briars.

80.00 chs.

N.89\*50'E., on random line between Sec. 21 & 28.

Va. 20\*35'E.

40.00 Set temporary  $\frac{1}{4}$  sec. cor.

79.92 Intersect N & S. line 48 lks. north of cor. to sec. 21, 22, 27 & 28. Thence N.89\*49'W., on a true line between Sec. 21 & 28.

Va. 20\*35'E.

Ascend.

9.00 Top of a ridge, course N.10\*W., about 400 ft. high.

Descend.

18.50 Stream 2 lks. wide, course N.15\*W., ascend.

20.35 Top of a spur, course N., Descend.

24.00 Stream 2 lks. wide, course N.

31.50 Stream 3 lks. wide, course N E.

39.96 Set post 3 ft. long and 3 ins. sq., 2 ft. in ground for  $\frac{1}{4}$  sec. cor. marked  $\frac{1}{4}$  S on N. face, from which,

A cedar, 30 ins. diam., bears S.55\*E., 9 lks. dist., marked  $\frac{1}{4}$  S B T.

A fir, 40 ins. diam., bears N.79\*E., 27 lks. dist., marked  $\frac{1}{4}$  S B T.

47.10 Stream 2 lks. wide, course N.

53.25 Stream 1 lk. wide, course N.

77.05 Stream 1 lk. wide, course N W.