

## County Surveyor's Record, Douglas County, Oregon

-2-

Subdivisions of T. 23 S., R. 9 W. W.M.  
as surveyed by W.H. Byars, Deputy Surveyor under  
Contract No. 279, dated March 5, 1878

## CHAINS

E. on random line between Secs. 1 and 12.

Va. 19\*E.

- 40.00 Set temp.  $\frac{1}{4}$  sec. corner.  
79.13 Intersect Tp. line 22 lks. North of corner  
N.89\*57'W. on true line  
20.00 Begin steep descent.  
38.00 Creek, 2 lks. wide, course S.  
39.56 Marked Fir, 48 ins. diam. for the  $\frac{1}{4}$  Sec. corner.  
55.00 Enter "Slide".  
72.00 Leave same.  
79.13 To Section corner  
Land broken, 3rd rate. The "Slide" was made in "61"  
and is about 60 acres of land, once heavily timbered,  
which slid into the creek destroying everything upon  
it and is now a mass of dry debris.

N. on random line between Secs. 1 and 2.

Va. 19\*E.

- 40.00 Set temp.  $\frac{1}{4}$  Sec. corner.  
80.15 Intersect Township line 80 lks. E. of corner  
S. 0\*38'E. on true line  
36.00 Top of ridge, course E. and W.  
40.08 Set Fir post, 4 ins. diam. 4 ft. long for the  $\frac{1}{4}$  Sec.  
corner, from which  
A Fir, 24 ins. diam., bears N.45\*E. 25 lks. dist.  
A Fir, 40 ins. diam., bears S.80\*W. 50 lks. dist.  
43.00 Trail to Loon Lake  
80.15 To Sec. corner  
Land, mountainous, 3rd rate  
Timber, Fir; 2nd class.

W. on true line between Secs. 2 and 11.

Va. 19\*E.

- 17.50 Camp Creek, 50 lks. wide, course N.  
22.50 Top of spur, course N.  
31.50 Camp Creek, 75 lks. wide, course S.  
40.00 Set Chitem-wood post 4 ins. diam. 4 ft. long, 20 ins.