

Subdivisions of T. 23 S., R. 9W. W.M.
 as surveyed by W.H. Byars, Deputy Surveyor under
 Contract No. 279, dated March 5, 1878

CHAINS

in ground for the $\frac{1}{4}$ Sec. cor., from which,

A Chitemwood, 5 ins. diam., bears N.5*E. 7 lks. dist.

A Fir, 10 ins. diam., bears S.10*E. 18 lks. dist.

43.00 Camp Creek, course W.

48.00 Leave same, course N.80*W.

50.50 Loon Lake Trail, course S.

March 23rd, 1878

54.00 Falls in Camp Creek, 40 ft. high, about 3 chs. N.

60.00 Mouth of Otter Creek. Enter Camp Creek.

64.00 Leave creek, course N.

75.00 Top of spur, course N.

80.00 Set Maple post 4 ins. diam. 4 ft. long, 18 ins. in
 ground for corner to Secs. 2, 3, 10 and 11.

A Maple 10 ins. diam., bears N.89*E. 44 lks. dist.

A Maple 5 ins. diam., bears S.40*E. 21 lks. dist.

A Maple, 6 ins. diam., bears S. 87*W. 28 lks. dist.

A Maple, 8 ins. diam., bears N.89*W. 27 lks. dist.

Land, broken, 3rd rate. Narrow bottom along creek 1st
 rate.

Timber, 2nd rate.

N. on random line between Secs. 2 and 3.

Va. 19*E.

40.00 Set temp. $\frac{1}{4}$ Sec. corner

80.25 Intersect Township line, 67 lks. East of corner.

South 0:29'E. on true line.

31.50 Camp Creek, 75 lks. wide, course N.W.

40.25 Set Fir post 4 ins. diam. 18 ins. in ground, 4 ft long,
 for $\frac{1}{4}$ Sec. corner, from which,

A Fir 8 ins. diam., bears North 46lks. dist.

A Fir, 7 ins. diam., bears S.75*W. 28 lks. dist.

80.26 To Section corner.

Land broken, 3rd rate.

Timber burned South of creek. Principally Fir, 2nd rate.