

## County Surveyor's Record, Douglas County, Oregon

-7-

North Boundary of  $\frac{1}{4}$ . 24 S., R 9 W., W.M.

CHAINS

A Fir, 60 ins. diam., bears S.70\*E., 21 lks. dist.  
 A Fir, 8 ins. diam., bears S.38\*W., 53 lks. dist.  
 A Fir, 12 ins. diam., bears N.60\*W., 47 lks. dist.  
 Land, hilly; 2nd rate. First rate along creek bottom.  
 Timber, Fir, Cedar and Maple along creek.  
 Underbrush, same, Vine-maple, Huckleberry and Hazel.

S.89\*35'W. on North bdy. of sec. 3

Va. 18\*E.

40.00 Set a Maple post, 3 ft. long, 5 ins. diam., 18 ins. in.  
 the ground for the  $\frac{1}{4}$  Sec. cor. on North bdy. of sec.  
 3, from which,

A Fir, 14 ins. diam., bears N.15\*E., 12 lks. dist.

A Fir, 16 ins. diam., bears S.5\*W., 17 lks. dist.

46.00 A creek, 3 lks. wide, course S.

63.25 A creek, 3 lks. wide, course S.

70.00 Enter bottom, course N. and S.

80.00 Set stone, 48 ins. x 36 ins. x 2 ins. in edge of Lake  
 Creek, 20 ins. in ground. Built stone mound for the  
 cor. to secs. 3 and 4 on North boundary from which,  
 An Alder, 18 ins. diam., bears N.6\*E., dist. 91 lks.  
 A Fir, 14 ins. diam., bears S.83\*E., dist. 74 lks.  
 A Fir, 16 ins. diam., bears S.28\*E. (across creek)  
 102 lks. dist.  
 An Alder, 20 ins. diam., bears N.32\*W. (across creek)  
 98 lks. dist.

Land, sloping south; 2nd rate; 1st rate in bottoms.  
 Timber and underbrush same as last line, considerable  
 down timber.

Sept. 13th, 1878

Sept. 13th, 1878

S.89\*35'W., on North Bdy. of sec. 4

Va. 18\*E.

1.25 Across creek, course NW.

6.00 Same creek, course  $\overline{SW}$ . 75 lks. wide.