

East Boundary of T. 23 S., R. 10 W., W.M.

CHAINS

A Laurel, 5 ins. diam., bears S.75*E., 12 lks. dist.

A Laurel, 5 ins. diam., bears S.30*W., 30 lks. dist.

A Laurel, 5 ins. diam., bears N.20*W., 45 lks. dist.

Land, rocky, broken, 3rd rate.

Timbers, chiefly burned; 3rd rate.

Underbrush, dense, Laurel, Fir, Huckleberry, etc.

N. on E. Bdy. of sec. 1

Va. 19*E.

40.00 Set an Alder post, 36 x 5, 18 ins. in ground for $\frac{1}{4}$ sec.
corner between secs. 1 and 12, from which

An Alder, 8 ins. diam., bears S.15*E., 39 lks.
dist.

A Fir, 40 ins. diam., bears N.60*W., 149 lks.
dist.

67.50 Creek, 5 lks. wide, course W.

85.00 September 25th, 1878.

123.00 Intersect line, 26.00 chs. E. of Tp. corner

Land, mountainous; 3rd rate.

Timber, principally Fir. Good in Northern part.

September 26th, 1878.

Subdivisions of T. 23 S., R. 9 W., W.M.
same Deputy and Contract.

Beginning at the corner to secs. 31 and 32 S. bdy.
of Township, I ran N. on line between secs. 31 and 32.

Va. 18*E.

8.40 A creek, 3 lks. wide, course W.

31.50 A creek, 15 lks. wide, course SW.