

County Surveyor's Record, Douglas County, Oregon

- 15 -

Subdivisions of T. 23 S., R. 9 W., W.M.

CHAINS

79.70

To sec. corner.

Lands, broken; 3rd rate.

Timber and underbrush same as last line.

May 10th, 1879.

N. on line between secs. 29 and 30.

Va. 19*E.

32.75

A creek, 1 lk. wide, course W.

37.00

A creek, 3 lks. wide, course W.

40.00

Set Maple post, 5 ft. long, 5 ins. diam., 20 ins. in the ground for the $\frac{1}{4}$ sec. cor. between secs. 29 and 30, from which,

A Fir, 12 ins. diam., bears N.20*E., 19 lks. dist.

A Fir, 18 ins. diam., bears S.75*W., 24 lks. dist.

70.00

Top of ridge, course E. and W.

80.00

Set Dogwood post 5 ft. long, 5 ins. diam., 20 ins. in ground for the corner to Secs. 19, 20, 29 and 30, from which,

A Fir, 60 ins. diam., bears N.20*E., 51 lks. dist.

A Fir, 60 ins. diam., bears S.10*E., 11 lks. dist.

A Fir, 24 ins. diam., bears S. 15*W., 12 lks. dist.

A Fir, 50 ins. diam., bears N.45*W., 38 lks. dist.

Land, hilly. South $\frac{1}{2}$ third rate; North $\frac{1}{2}$ second rate.

Timber and underbrush description unchanged.

West on random line between secs. 19 and 30.

Va. 19* East.

40.00

Set temp. $\frac{1}{4}$ sec. corner.

79.16

Intersect line 30 lks. South of corner.

S.89*47' E. on true line between secs. 19 and 30.

82.00

Leave valley, course S. and SW.

37.50

A creek, 2 lks. wide, course S.

39.26

Set a Myrtle post, 5 ft. long, 5 ins. diam., 20 ins.

in the ground for the $\frac{1}{4}$ sec. cor. bet. secs. 19 & 30