

- 22 -

South Boundary of T.23 S., R.9 W., W.M.  
as surveyed by Oscar F. Thiel.

## CHAINS

- August 18: At 7 h 30m A.M. l.m.t., I set off 43\*31' on the lat. arc, 13\*0'N., on the decl. arc, and determine a true meridian with the solar, at the cor. of Secs. 35 and 36.
- Thence I run S.89\*35'W., Bet. Secs. 35 and 2.
- Ascending a mountainous spur, heavily timbered with Fir, Cedar and Hemlock.
- 6.28  $\frac{1}{4}$  Sec. cor.; the old post being gone, I re-establish the same by setting a hemlock post 3 ft. long, 3 ins. sq. 24 ins. in the ground marked  $\frac{1}{4}$  S on N. and 2 on S. face, and witnessed as described by the surveyor general.
- 12.00 Top of spur, bears N. and S. 80 ft above  $\frac{1}{4}$  Sec. cor., begin a steep descent.
- 17.10 A stream, 2 lks. wide, course NW., continue to descend through a heavy undergrowth of huckleberries and small hemlocks.
- 37.50 Foot of descent, 275 ft. below top of spur, Enter a narrow bottom, Bears SW and NE.
- 40.00 Set a sandstone, 20 x 10 x 10 ins., 15 ins. in the ground for  $\frac{1}{4}$  Sec. cor., marked  $\frac{1}{4}$  on N. face, from which,
- A Vinemaple, 6 ins. diam., bears N.12\*E. 19 lks. dist. marked  $\frac{1}{4}$  S 35 B T.
- A Vinemaple 5 ins. diam., bears S.13\*W, 23 lks. dist. marked  $\frac{1}{4}$  S 35 B T.
- 41.25 A stream 20 lks. wide, course SW., through heavy underbrush of vinemaple.
- 46.52 The cor. of Secs. 2 and 3., the original post is standing, badly decayed, it is a Fir post 5 ins. sq., 24 ins. high, marked and witnessed as described by the surveyor general, witness trees marked T 22, I destroyed all marks, referring to this tp. Thence, ascending a S. slope of mountain, covered with dense undergrowth of small hemlock, huckleberries and hazel.
- The cloudy weather prevented the taking of lat at noon.