

## County Surveyor's Record, Douglas County, Oregon

-27-

Subdivisions of T. 23 S., R. 9 W., W.M.

## CHAINS

33 on E. face, from which,

A Fir, 30 ins. diam., bears E. 43 lks. dist.,  
marked  $\frac{1}{4}$  S 33 B T.

A Fir, 24 ins. diam., bears S.28\*W., 8 lks. dist.  
marked  $\frac{1}{4}$  S 32 B T.

This point is 150 ft. below top of ridge.

42.75 A stream, 3 lks. wide, course NW., begin to ascend.

55.50 Top of a spur, bears E. and W., 120 ft. above stream;  
begin steep descent of N. slope of mountain.

67.40 A stream, 8 lks. wide, course W., 150 ft. below top of  
spur, begin ascent.

75.20 Top of spur bears E. and W., 110 ft. above stream,  
descend a NW. slope.

80.00 Set a sandstone 16 x 12 x 8 ins., 11 ins. in the ground  
for cor. to secs. 28, 29, 32 and 33, marked with  
1 notch on S. and 4 notches on E. edges, from which,  
A Yew, 6 ins. diam., bears N.76 $\frac{1}{2}$ \*W., 37 lks. dist.  
marked T 23 S R 9 W S 29 B T  
A Fir, 24 ins. diam., bears S.69\*W., 23 lks. dist.  
marked T 23 S R 9 W S 32 B T.  
A Fir, 8 ins. diam., bears N.46\*E., 193 lks. dist.  
marked T 23 S R 9 W S 28 B T.  
A Vine-maple, 5 ins., diam., bears S.73\*E., 132  
lks. dist., marked T 23 S R 9 W S 33 B T.

Cloudy weather prevented taking lat. at noon.

Land, mountainous.

Soil, gravelly; 3rd rate.

Timber, Fir, Cedar, Hemlock, Yew, dense.

Undergrowth of huckleberries and vinemaple and salal-  
berries.

Mountainous and heavily timbered land and land covered  
with a dense undergrowth.

80.00 chains.