

County Surveyor's Record, Douglas County, Oregon

- 29 -

Subdivisions of T. 23 S., R. 9 W., W.M.

CHAINS	I destroyed all marks on old cor. and witness trees, referring to secs. 28 and 29.
77.58 and 3.21	<p>Land, mountainous. Soil, gravelly; 3rd rate. Timber, Fir, Cedar, Hemlock, Alder, Maple. Undergrowth, dense and of huckleberries, vinemaple, salalberries.</p> <p>Mountainous and heavily timbered land and land covered by dense undergrowth.</p> <p style="text-align: right;">August 23, 1898.</p>
10.70	At cor. of secs. 25 and 36 on E. bdy. of Tp., thence I run, West, bet. secs. 25 and 36.
14.90	Descend a NW. slope of mountain, covered heavily with Fir timber.
21.75	A stream, 2 lks. wide, course N., 100 ft. below sec. cor.
36.00	A stream, 5 lks. wide, course SW., follow a S. slope of mountain.
39.00	Begin a very steep ascent of SE. slope of mountain.
40.00	Foot of a perpendicular bluff, 50 ft. high, bears SW. and NE.; a very steep rocky ascent of 45*, through small firs and hazel; dense undergrowth.
	Top of spur, bears N. and S. 500 ft. above stream.
	Set a Laurel post, 3 ft. long, 3 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S 25 on N. face and 36 on S. face, from which,
	A Laurel, 4 ins. diam., bears N.56*E., 5 lks. dist. marked $\frac{1}{4}$ S 25 B T.
	A Fir, 36 ins. diam., bears S.58*W., 65 lks. dist., marked $\frac{1}{4}$ S 36 B T.
	Begin a very steep descent of a SW. slope of mountain covered, beside timber, with a dense undergrowth of Hazel, Sweet Balm and Vine-maple.
44.00	Enter large fir timber, bears N. and S.